




FERROUS

NON  
FERROUS

FERROUS  
SPIGGOT ON SPROCKET

CENTRE  
LINE →

FERROUS  
CENTRE SCREW FLANGE

THIS TINY  
2.3 mm x 0.3 mm  
SPACE SEEMS TO BE  
THE PROBLEM AREA

CENTRING SCREW  
HEAD